

#### **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

### Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 397 Const Calendar Day: 435 Date: 13-Aug-2013 Tuesday Inspector Name: Soheilifard, Saman Title: Transportation Engineer

Inspection Type: Intermittent

**Shift Hours:** 07:15 am 06:00 pm **Break:** 00:30 **Over Time:** 02:00

Federal ID: Location:

Reviewer: Awal, Mohammad Approved Date: 30-May-14 Status: Approved

Weather

**Temperature 7 AM** 50 - 60 **12 PM** 60 - 70 **4PM** 

Precipitation none Condition Clear & Sunny

Working Day 🗸 If no, explain:

Diary:

Work description.

Tuesday, August 13, 2013

The 9:00 weekly meeting that lasted until 10:45 and attended by ABF, CT, designers, Conoco, and other municipalities;

A field meeting with AT&T that was supposed to start at 13:45 did not begin until 14:00 had many attendants in regards to the switching of the transferring from the existing lines to updated ones feeding the maintenance yard and the new IERBYS building. For more information, please refer to reports by Trinh or/and Tom Shimada; Brian Peterson stated that ABF would pay for 8 new voice and data lines if CT cannot front the funds:

At 15:00, grout was delivered to the site. I took 2 pairs of samples: a 14-day & a 28-day. Slump = 9in.; Temp. = 79F; Ambient = 75F; The QC took samples as well.

The pour was complete at 15:28 and the CMU walls poured were as follow:

The full height of the 12" T6 wall; the full height of the short TD wall; the full height of the T5 wall; ¾ of wall T6:

Walls not poured at this time are: T7 & T8 + a section of the TF wall that is confined by walls T8 & T4;

Today all MCU walls east of the T4 wall were constructed to the height of 7 courses. In addition, the last CMU wall to be constructed, TG, was erected to the height of 7 courses extending beyond the T4 wall and all the way to the T2 wall; 2 courses constructed for wall T2 and one course for the CMU wall T1;

The second load of grout delivered to the job site at 16:03 with which walls T6, T8, TF, and T7 were completed in succession and finished off with the pouring of 6' by16" of the TG wall;

Pour ended at 16:30 and the re-vibration started at 16:35 with the TG wall;

04-0120F4 Bid Item: 081 0-000-000.081 CLEAN AND PAINT CABLE SYSTEM

CERTIFIED COATINGS COMPANY

CCO-298 Bid Item: 001 0-RHB-EFA.298 IERBYS Rehabilitation

CERTIFIED COATINGS COMPANY



Page 1 of 4

Run date 22-Nov-14

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Time 4:41 PM

# Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Soheilifard, Saman Diary #: 397 Date: 13-Aug-2013 Tuesday

CO-298	Bid Item: 001	0-RHB-EFA.298	IERBYS Rehabilitation	
. Mezza Masonry				
Labor				
Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Contractor: R.	Mezza Masonry			
Cement Masor	n Huddie	Gilberto Robles	8.00 2.00 0.00 10.00	
Cement Masor	n Huddie	Juan Gyrrola	8.00 2.00 0.00 10.00	
Cement Masor	n Mason	Clint Dossa	8.00 2.00 0.00 10.00	
Cement Masor	n mason	Greg Harriss	8.00 2.00 0.00 10.00	
Cement Masor	n mason	Robert Kirk	8.00 2.00 0.00 10.00	
Cement Masor	n super	Bob Mezza	8.00 2.00 0.00 10.00	
CONCO PUMPING				
Labor				
Labor Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Trade	Class ONCO PUMPING	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Trade	ONCO PUMPING	Name Clint Dossa	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Trade Contractor: Co	ONCO PUMPING mason			Dispute
Trade Contractor: Co Cement Masor	ONCO PUMPING mason Huddie	Clint Dossa	0.00 0.00 0.00	Dispute
Trade Contractor: Co Cement Masor Cement Masor	ONCO PUMPING n mason n Huddie n Huddie	Clint Dossa Gilberto Robles	0.00 0.00 0.00 0.00 0.00 0.00 0.00	Dispute
Contractor: Contractor: Coment Masor Cement Masor Cement Masor Cement Masor	ONCO PUMPING mason Huddie Huddie mason	Clint Dossa Gilberto Robles Juan Gurrola	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Dispute
Trade Contractor: Co Cement Masor Cement Masor Cement Masor Cement Masor	ONCO PUMPING mason Huddie Huddie mason mason mason	Clint Dossa Gilberto Robles Juan Gurrola Greg Harriss	0.00     0.00     0.00     0.00       0.00     0.00     0.00     0.00       0.00     0.00     0.00     0.00       0.00     0.00     0.00     0.00	Dispute
Trade Contractor: Ct Cement Masor Cement Masor Cement Masor Cement Masor Cement Masor	ONCO PUMPING mason Huddie Huddie mason mason mason	Clint Dossa Gilberto Robles Juan Gurrola Greg Harriss Robert Kirk	0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00	Dispute
Trade Contractor: Ct Cement Masor Cement Masor Cement Masor Cement Masor Cement Masor	ONCO PUMPING mason Huddie Huddie mason mason mason	Clint Dossa Gilberto Robles Juan Gurrola Greg Harriss Robert Kirk	0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00         0.00       0.00       0.00       0.00	Dispute

#### Attachment





Vibration of the Grout



# Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Soheilifard, Saman Diary #: 397 Date: 13-Aug-2013 Tuesday













Slump of 9 inches

# Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Soheilifard, Saman Diary #: 397 Date: 13-Aug-2013 Tuesday



